

## Storage Recommendations for KYDEX® 5555, KYDEX® 6565, and KYDEX 6565(d)®

TB - 151


### Recommended Storage Procedure

### Palletized Material

KYDEX® recommends that for long term storage of KYDEX® 5555, 6565, or 6565(d)®, a method similar to our standard export packaging practice would be best. This procedure will help protect the sheets during handling, keep the sheets clean, and will minimize any possible moisture absorption.

*\*\*Original Kleerdex orders incorporate all the items listed below on each pallet or staple box. If these items are no longer available then a comparable substitute can be used.*

- 1) Place a piece of dunage (scrap sheet) directly on the pallet.
- 2) Center a sheet of moisture wrap on the dunage sheet (Kleerdex uses a paper-based moisture wrap that is coated with a waxy film on one side, which always faces the outside of the package). Allow for enough excess paper on all sides to reach the top of the sheets when you are finished stacking the material. If one sheet of moisture wrap is not wide enough, you may need to tape two sheets together.
- 3) Stack the sheet on top of the moisture wrap.
- 4) Place a sheet of moisture wrap on top of the stack of material with the waxy side up. Fold the excess wrapping material from the bottom over the moisture wrap on top (taking care not to tear holes in the wrap), and seal all seams with clear packing tape.
- 5) Place a piece of dunage on top of the wrapped package. Secure the package together by placing bands as appropriate around the plastic to keep the sheets from shifting during handling. Then shrink wrap the package (similar to wrapping a clear plastic wrap around the edges of the sheets).
- 6) Now place a cardboard lid, or other form of protective covering on top of the package, and band the stack to the pallet as is appropriate.
- 7) Store in a cool dry place, if possible.



KYDEX, LLC  
ISO 9001 and 14001 Certified

**Customer Service**  
6685 Low St, Bloomsburg, PA 17815 USA  
Phone: 800.325.3133, +1.570.389.5810  
Outside the US: +1.570.389.5814  
Fax: 800.452.0155, +1.570.387.7786  
Email: [info@kydex.com](mailto:info@kydex.com)

**Technical Service**  
Phone: 800.682.8758 ext. 581  
Fax: +1.570.387.8722  
Outside the US: +1.570.387.6997 ext. 581

[www.kydex.com](http://www.kydex.com)

Because we cannot anticipate or control the many different conditions under which this information and our products may be used, we do not guarantee the applicability of the accuracy of this information or the suitability of our products in any given situation. Users should conduct their own tests to determine the suitability of each product for their particular purposes. Data in the physical property table represents typical values and are to serve only as a guide for engineering design. Results are obtained from specimens under ideal laboratory conditions. Right to change physical properties as a result of technical progress is reserved. THE PRODUCTS DISCUSSED ARE SOLD WITHOUT WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE, EITHER EXPRESSED OR IMPLIED, EXCEPT AS PROVIDED IN OUR STANDARD TERMS AND CONDITIONS OF SALE. Buyer assumes all responsibility for loss or damage arising from the handling and use of our products, whether done in accordance with directions or not. In no event shall the supplier or the manufacturer be liable for incidental or consequential damages. Also, statements concerning the possible use of our products are not intended as recommendations to use our products in the infringement of any patent. Consult local code and regulatory agencies for specific requirements regarding code compliance, transporting, processing, recycling and disposal of our product. Product not intended for use as a heat resistant surface. Texture, product grade and other conditions may cause variations in appearance.

This information supersedes all previously published data.